

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



1 of 2

**Facility Information**

**RESULT: Satisfactory**

Permit Number: 13-51-08264 Name of Facility: Carver, G. W. El. Address: 238 Grand Avenue City, Zip: Miami 33133  Type: Public Schools Owner: M-DCSB Food and Nutrition Person In Charge: Patricia Fairclough PIC Email: pfairclough@dadeschools.net	<b>Correct By: Next Inspection</b> <b>Re-Inspection Date: None</b>
Phone: 305-443-5286	

**Inspection Information**

Purpose: Routine Inspection Date: 2/3/2020	Begin Time: 03:05 PM End Time: 04:10 PM
---	--

**Additional Information**

FEMALES ..... 213 MALES ..... 246	CENSUS ..... 459
--------------------------------------	------------------

*This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.*

**Violation Markings**

SCHOOL SANITATION IN 1. School Site IN 2. Playground, Equip & Athletic Fields* IN 3. Athletic & Playground Equipment BUILDING CONST/MAINT. IN 4. Construction OUT 5. Maintenance & Repair IN 6. Lighting Standards IN 7. Heating, Ventilation, A/C Standards IN 8. Natural Ventilation IN 9. Mechanical Ventilation SANITARY FACILITIES IN 10. Provided/Accessible/Separation	IN 11. Group Toilet Rooms IN 12. Toilet Facilities IN 13. Handwashing Facilities IN 14. Soap Dispensers IN 15. Shower Facilities IN 16. Showers Water Temperatures WATER SUPPLY IN 17. Approved Source IN 18. Drinking Fountains LIQUID WASTE & WASTE WATER IN 19. Sewage Disposal IN 20. Solid Waste PEST CONTROL	IN 21. Pest Control SAFETY IN 22. First Aid Kit DIAPER CHANGING STATION NA 23. Sanitizers NA 24. Changing Station & Mats NA 25. Hand Sink NA 26. Garbage Can ANIMAL HEALTH & SAFETY NA 27. Animal Maintenance/Aggressive DORM/RESIDENTIAL FACILITIES NA 28. Maintenance/Complaint NA 29. Other
---	--	--

*Marking Key: IN = the act or item was observed to meet standards; OUT = the act or item was observed not to meet standards; NO = the act or item was not observed to be occurring at the time of inspection; NA = the act or item is not performed by the facility or not part of the operation*

*Violation Key: \* = 2. Playground, Equipment & Athletic Fields*

Inspector Signature:

Client Signature:

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



2 of 2

### General Comments

Satisfactory

-Alive roach was observed inside of the fire alarm box in portable classroom #49-177. Person in charge indicated that classroom has not been use since a month ago.

-Clean and sanitize portable classroom #49-177 for the biological growth infection. Person in charge indicated that work order has been submitted because of the biological growth infection. Person in charge indicated that classroom has not been use since a month ago. MDCPS facilities confirmed that portable it planned to be demolished.

-No children in classroom #15 and portable classrooms were affected.

Email Address(es): tequigley@dadeschools.net;  
pfairclough@dadeschools.net;  
jaybolton@dadeschools.net;  
jware@dadeschools.net;  
ipalacios@dadeschools.net

### Violations Comments

Violation #5. Maintenance & Repair

-There is an active leak inside of classroom #015 need to be repair. Missing ceiling panels and drops of water coming from the roof were observed. Person in charge indicated that classroom it's not been used because of the active leak. Person in charge indicated that work orders have been submitted and classroom is not being used.

-Replace missing plaster on ceiling inside of girls restroom #001A.

-Replace three light bulb burned-out inside of room #011.

-Adjust loose and not functional second faucet located inside of boys restroom #001C.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

Inspection Conducted By: Lucia Gonzalez Melendez (913031)  
Inspector Contact Number: (786) 676-2013  
Print Client Name: Carver, G. W. El.  
Date: 2/3/2020

Inspector Signature:

Handwritten signature of Lucia Gonzalez Melendez.

Client Signature:

Handwritten signature of G. W. El. Carver.